

Panel thickness 100 mm

Dear customers, please select the required dimensions of the freezer room. Go to the feedback form or call us.

H= 2240 mm

Length	Width	v, m ³
1400	1400	2,94
	1700	3,67
	2000	4,41
	2300	5,14
	2600	5,88
	2900	6,61
	3200	7,34
	3500	8,08
	3800	8,81
	4100	9,55
	4400	10,28
	4700	11,02
	5000	11,75
	5300	12,48
5600	13,22	
1700	1700	4,59
	2000	5,51
	2300	6,43
	2600	7,34
	2900	8,26
	3200	9,18
	3500	10,10
	3800	11,02
4100	11,93	
4400	12,85	
4700	13,77	

H= 2500 mm

Length	Width	v, m ³
1400	1400	3,31
	1700	4,14
	2000	4,97
	2300	5,80
	2600	6,62
	2900	7,45
	3200	8,28
	3500	9,11
	3800	9,94
	4100	10,76
	4400	11,59
	4700	12,42
	5000	13,25
	5300	14,08
5600	14,90	
1700	1700	5,17
	2000	6,21
	2300	7,25
	2600	8,28
	2900	9,31
	3200	10,35
	3500	11,39
	3800	12,42
4100	13,46	
4400	14,49	
4700	15,53	

H= 2760 mm

Length	Width	v, m ³
1400	1400	3,69
	1700	4,61
	2000	5,53
	2300	6,45
	2600	7,37
	2900	8,29
	3200	9,22
	3500	10,14
	3800	11,06
	4100	11,98
	4400	12,90
	4700	13,82
	5000	14,75
	5300	15,67
5600	16,59	
1700	1700	5,76
	2000	6,91
	2300	8,06
	2600	9,22
	2900	10,37
	3200	11,52
	3500	12,67
	3800	13,82
4100	14,98	
4400	16,13	
4700	17,28	

	5000	14,69
	5300	15,61
	5600	16,52
2000	2000	6,61
	2300	7,71
	2600	8,81
	2900	9,91
	3200	11,02
	3500	12,12
	3800	13,22
	4100	14,32
	4400	15,42
	4700	16,52
	5000	17,63
	5300	18,73
	5600	19,83
	2300	2300
2600		10,28
2900		11,57
3200		12,85
3500		14,14
3800		15,42
4100		16,71
4400		17,99
4700		19,28
5000		20,56
5300		21,85
5600	23,13	
	2600	11,75
	2900	13,22
	3200	14,69
	3500	16,16
	3800	17,63

	5000	16,56
	5300	17,59
	5600	18,63
2000	2000	7,45
	2300	8,69
	2600	9,94
	2900	11,18
	3200	12,42
	3500	13,66
	3800	14,90
	4100	16,15
	4400	17,39
	4700	18,63
	5000	19,87
	5300	21,11
	5600	22,36
	2300	2300
2600		11,59
2900		13,04
3200		14,49
3500		15,94
3800		17,39
4100		18,84
4400		20,29
4700		21,73
5000		23,18
5300		24,63
5600	26,08	
	2600	13,25
	2900	14,90
	3200	16,56
	3500	18,22
	3800	19,87

	5000	18,43
	5300	19,58
	5600	20,74
2000	2000	8,29
	2300	9,68
	2600	11,06
	2900	12,44
	3200	13,82
	3500	15,21
	3800	16,59
	4100	17,97
	4400	19,35
	4700	20,74
	5000	22,12
	5300	23,50
	5600	24,88
	2300	2300
2600		12,90
2900		14,52
3200		16,13
3500		17,74
3800		19,35
4100		20,97
4400		22,58
4700		24,19
5000		25,80
5300		27,42
5600	29,03	
	2600	14,75
	2900	16,59
	3200	18,43
	3500	20,28
	3800	22,12

2600	4100	19,09
	4400	20,56
	4700	22,03
	5000	23,50
	5300	24,97
	5600	26,44
2900	2900	14,87
	3200	16,52
	3500	18,18
	3800	19,83
	4100	21,48
	4400	23,13
	4700	24,79
	5000	26,44
	5300	28,09
5600	29,74	
3200	3200	18,36
	3500	20,20
	3800	22,03
	4100	23,87
	4400	25,70
	4700	27,54
	5000	29,38
	5300	31,21
	5600	33,05
3500	3500	22,22
	3800	24,24
	4100	26,25
	4400	28,27
	4700	30,29
	5000	32,31
	5300	34,33
	5600	36,35

2600	4100	21,53
	4400	23,18
	4700	24,84
	5000	26,50
	5300	28,15
	5600	29,81
2900	2900	16,77
	3200	18,63
	3500	20,49
	3800	22,36
	4100	24,22
	4400	26,08
	4700	27,95
	5000	29,81
	5300	31,67
5600	33,53	
3200	3200	20,70
	3500	22,77
	3800	24,84
	4100	26,91
	4400	28,98
	4700	31,05
	5000	33,12
	5300	35,19
	5600	37,26
3500	3500	25,05
	3800	27,32
	4100	29,60
	4400	31,88
	4700	34,16
	5000	36,43
	5300	38,71
	5600	40,99

2600	4100	23,96
	4400	25,80
	4700	27,65
	5000	29,49
	5300	31,33
	5600	33,18
2900	2900	18,66
	3200	20,74
	3500	22,81
	3800	24,88
	4100	26,96
	4400	29,03
	4700	31,10
	5000	33,18
	5300	35,25
5600	37,32	
3200	3200	25,34
	3500	25,34
	3800	27,65
	4100	29,95
	4400	32,26
	4700	34,56
	5000	36,86
	5300	39,17
	5600	41,47
3500	3500	27,88
	3800	30,41
	4100	32,95
	4400	35,48
	4700	38,02
	5000	40,55
	5300	43,08
	5600	45,62

3800	3800	26,44
	4100	28,64
	4400	30,84
	4700	33,05
	5000	35,25
	5300	37,45
	5600	39,66
4100	4100	31,03
	4400	33,42
	4700	35,80
	5000	38,19
	5300	40,58
	5600	42,96
4400	4400	35,99
	4700	38,56
	5000	41,13
	5300	43,70
	5600	46,27
4700	4700	41,31
	5000	44,06
	5300	46,82
	5600	49,57
5000	5000	47,00
	5300	49,94
	5600	52,88
5300	5300	53,06
	5600	56,18
5600	5600	59,49

3800	3800	29,81
	4100	32,29
	4400	34,78
	4700	37,26
	5000	39,74
	5300	42,23
	5600	44,71
4100	4100	34,98
	4400	37,67
	4700	40,37
	5000	43,06
	5300	45,75
	5600	48,44
4400	4400	40,57
	4700	43,47
	5000	46,37
	5300	49,27
	5600	52,16
4700	4700	46,58
	5000	49,68
	5300	52,79
	5600	55,89
5000	5000	52,99
	5300	56,30
	5600	59,62
5300	5300	59,82
	5600	63,34
5600	5600	67,07

3800	3800	33,18
	4100	35,94
	4400	38,71
	4700	41,47
	5000	44,24
	5300	47,00
	5600	49,77
4100	4100	38,94
	4400	41,93
	4700	44,93
	5000	47,92
	5300	50,92
	5600	53,91
4400	4400	45,16
	4700	48,38
	5000	51,61
	5300	54,84
	5600	58,06
4700	4700	51,84
	5000	55,30
	5300	58,75
	5600	62,21
5000	5000	58,98
	5300	62,67
	5600	66,36
5300	5300	66,59
	5600	70,50
5600	5600	74,65